

**PIQUA/HARTZELL FLD** (I17) 3 NW UTC-5(-4DT) N40°09.88' W84°18.51' DETROIT  
L-27E  
IAP  
 993 B NOTAM FILE DAY  
**RWY 08-26:** H3998X75 (ASPH) S-30, D-36 MIRL  
**RWY 08:** REIL. PAPI(P2L)—GA 3.0° TCH 36'. Crops.  
**RWY 26:** REIL. PAPI(P2L)—GA 3.0° TCH 37'. Crops.  
**SERVICE:** S2 FUEL 100LL, JET A+, A1+ LGT ACTIVATE REIL Rwy 08 and Rwy 26; MIRL Rwy 08-26—CTAF. PAPI Rwy 08 and Rwy 26 opr consly. Rwy 08 PAPI unusbl byd 6° right of cntrl.  
**AIRPORT REMARKS:** Attended Mon-Fri 1300-2200Z. Unatndd major hols. Fuel avbl H24 via credit card. Arpt conds unmon Mon-Fri 2100-1300Z, Sat-Sun, and hols. Propeller repairs avbl. Aerobatic box lctd wi 1 NM of arpt, blw 4500' MSL SR-SS. Rwy 26 calm wind rwy.  
**AIRPORT MANAGER:** 937-778-5742  
**COMMUNICATIONS:** CTAF/UNICOM 123.0  
 ® **COLUMBUS APP/DEP CON** 134.45  
**CLEARANCE DELIVERY PHONE:** For CD ctc Columbus Apch at 614-338-8537.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE DAY.  
**DAYTON (V) (L) VOR/DME** 114.5 DQN Chan 92 N40°00.99' W84°23.81' 026° 9.8 NM to fld. 989/1W.  
 DME unusable:  
 Byd 35 NM blo 2,900'  
 VOR unusable:  
 245°-250° byd 40 NM  
**ROSEWOOD (H) (H) VORTACW** 117.5 ROD Chan 122 N40°17.27' W84°02.59' 244° 14.3 NM to fld. 1080/5W.  
 TACAN AZIMUTH unusable:  
 000°-120°  
 125°-135°  
 VOR unusable:  
 125°-135°

---

**PORT BUCYRUS/CRAWFORD CO** (See BUCYRUS on page 265)

---

**PORT CLINTON**

**ERIE-OTTAWA INTL** (PCW)(KPCW) 3 E UTC-5(-4DT) N41°30.98' W82°52.17' DETROIT  
H-10G, L-30F  
IAP  
 590 B LRA NOTAM FILE PCW  
**RWY 09-27:** H5646X100 (ASPH-GRVD) S-100 HIRL  
**RWY 09:** REIL. PAPI(P4L)—GA 3.0° TCH 40'. Tree.  
**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 40'. Thld dsplcd 201'. Trees.  
**RWY 18-36:** H4002X75 (ASPH) MIRL  
**RWY 36:** Trees.  
**SERVICE:** S4 FUEL 100LL, JET A+ OX 1, 2, 3, 4 LGT Actvt REIL Rwy 09 & 27; HIRL Rwy 09-27; MIRL Rwy 18-36—CTAF. PAPI Rwy 09 & 27 opr consly.  
**AIRPORT REMARKS:** Attended 1200-2300Z. Occnl deer, birds and otr wildlife on & invof arpt. Rwy 27 calm wind rwy. Taxilane A clsd to acft with wingspan more than 49 ft. Cust avbl 24 hrs 7 days per week. Req must be made two prior to arr. Lcl ofc 419-732-4446. Hngr transient storage: PPR.  
**AIRPORT MANAGER:** 419-734-6297  
**WEATHER DATA SOURCES:** AWOS-3 118.775 (419) 734-9955.  
**COMMUNICATIONS:** CTAF/UNICOM 122.8  
 ® **CLEVELAND APP/DEP CON** 126.35  
**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apch at 216-352-2323.

CONTINUED ON NEXT PAGE

## CONTINUED FROM PRECEDING PAGE

## RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.

**DRYER (VH) (DH) VOR/DME** 113.6 DJB Chan 83 N41°21.48' W82°09.72' 292° 33.3 NM to fld. 780/5W.

## VOR unusable:

001°-010° byd 40 NM  
 020°-024° byd 40 NM  
 034°-040° byd 55 NM  
 080°-095° byd 40 NM  
 110°-120° byd 40 NM  
 135°-145° byd 40 NM  
 135°-150°  
 155°-165°  
 160°-165° byd 40 NM  
 185°-195° byd 40 NM  
 187°-197°  
 210°-224° byd 40 NM  
 211°-218°  
 225°-235° byd 40 NM blo 11,000'  
 225°-235° byd 95 NM  
 225°-245° byd 20 NM blo 3,500'  
 245°-265° byd 40 NM  
 275°-285° byd 40 NM blo 18,000'  
 286°-355° byd 40 NM

## DME unusable:

187°-197°  
 289°-310°  
 322°-332°  
 350°-060°

**PORTAGE CO** (See RAVENNA on page 312)**PORTSMOUTH**

**GREATER PORTSMOUTH RGNL** (PMH)(KPMH) 10 NE UTC-5(-4DT) N38°50.43' W82°50.84'

CINCINNATI

663 B NOTAM FILE PMH

H-10G, L-26G

**RWY 18-36:** H5001X100 (ASPH) S-30, D-42, 2D-70 MIRL

IAP


**RWY 18:** REIL. PAPI(P4L)—GA 3.0° TCH 25'.**RWY 36:** REIL. PAPI(P4L)—GA 3.0° TCH 31'.

**SERVICE:** S4 **FUEL** 100LL, JET A1+ **LGT** Actvt REIL Rwy 18 & 36;  
 MIRL Rwy 18-36—CTAF. PAPI Rwy 18 & 36 opr consly.

**AIRPORT REMARKS:** Attended 1400-2200Z†. Hill obstruction lgts  
 460' (1124') 1 mile south and 410' (1074') 1/2 mile northwest.  
 No line of sight between rwy ends, acft not visible from one rwy end to  
 other. Ldg fee for turbine acft waived with fuel purchase, ctc arpt  
 for dtls.

**AIRPORT MANAGER:** 740-820-2700**WEATHER DATA SOURCES:** AWOS-3 125.175 (740) 820-2500.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **HUNTINGTON APP/DEP CON** 128.4

**CLEARANCE DELIVERY PHONE:** For CD ctc Huntington ATCT at  
 304-453-2490.



**PUT IN BAY** (3W2) 1 SW UTC-5(-4DT) N41°38.20' W82°49.70'

DETROIT

595 B NOTAM FILE CLE

**RWY 03-21:** H2870X75 (ASPH)**RWY 03:** Thld dsplcd 450'. Trees. Rgt tfc.**RWY 21:** Thld dsplcd 657'. Fence.**SERVICE:** S4

**AIRPORT REMARKS:** Unattended. Acft ops prohibited dusk-dawn. Birds, deer, and other wildlife invof arpt. Exp mod turb on  
 app/dep when wind exceeds 10 kts. Acft Indg Rwy 21 or dep Rwy 03 rmn 1000' clear of Perry's Monument 352' (942')  
 1.3 NM NE of arpt. Prkg/ramp fees for all pvt or coml acft, all pilots are rqr'd to ck in at arpt ofc at the time of arr; all acft  
 rqr'd to shut down engine(s) when enplaning/deplaning pax.

**AIRPORT MANAGER:** 419-285-3371**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apch at 216-352-2323.

**HELIPORT REMARKS:** Helipad is for touchdown, loading and lift off only—park on grass, west and SW of helipad.