


UPOLU (UPP)(PHUP) 3 NW UTC-10 N20°15.91' W155°51.60'
96 B TPA—See Remarks NOTAM FILE UPP
RWY 07-25: H3800X75 (ASPH) S-30, 2S-156 MIRL

HAWAIIAN ISLANDS
P-2G

0.3% up W
RWY 25: Hill. Rgt t/c.
SERVICE: LGT ACTVT MIRL Rwy 07-25—CTAF.
AIRPORT REMARKS: Unattended. No facilities. PPR for transient parking. PPR from arpt manager phone (808) 327-9520 for transportation of Division 1.1, 1.2, 1.3 explosives in or out of arpt. Occasional flocks of birds on and invof arpt. Skydiving activity on and invof arpt. All helicopters confine ops to paved areas only. TPA—small acft 800(704), large acft 1500(1404). NOTE: See Area Notices—TRAFFIC ADVISORIES AT NON-TOWER AIRPORTS.
AIRPORT MANAGER: (808) 327-9520
COMMUNICATIONS: CTAF 122.9
UPOLU POINT RCO 122.1R 112.3T (HONOLULU RADIO)
CLEARANCE DELIVERY PHONE: For CD ctc Honolulu Control Facility at 808-840-6262.
RADIO AIDS TO NAVIGATION: NOTAM FILE UPP.
UPOLU POINT (H) VORTAC 112.3 UPP Chan 70 N20°12.03' W155°50.60' 335° 4.0 NM to fld. 1760/11E.



VOR unusable:
022°-040° blo 5,000'
123°-130°
203°-292° byd 30 NM blo 8,000'
VORTAC unusable:
145°-160° byd 27 NM blo 19,000'
168°-180° byd 25 NM blo 10,000'

UPOLU POINT N20°12.03' W155°50.60' NOTAM FILE UPP.
(H) VORTAC 112.3 UPP Chan 70 335° 4.0 NM to fld. 1760/11E.

HAWAIIAN-MARIANA
P-2G

VOR unusable:
022°-040° blo 5,000'
123°-130°
203°-292° byd 30 NM blo 8,000'
VORTAC unusable:
145°-160° byd 27 NM blo 19,000'
168°-180° byd 25 NM blo 10,000'
RCO 122.1R 113.3T (HONOLULU RADIO)