

PAFM

Ambler
Ambler, AK

1.00 mi N of city N67 6.3720' W157 51.4293' Mag Var: 13E

Nav aids:
No Nav aids Available

Traffic Patterns:
No TPA reported. Assume 1,000 AGL.
Left: 01,19 (Assumed Left: 10,28)

Runways:	Name:	Dimensions:	Material:	Condition:	Treatment:
	01/19	4000X75	gravel	good	no treatment
	Trees; 315' from end; 140' Right of center; 10' high; 31:1 clearance slope;				
	Trees; 0' from end; 180' Right of center; 13' high; 0:1 clearance slope;				
	10/28	2400X60	gravel	good	no treatment

Lighting:
Actvt PAPI Rwy 01; MIRL Rwy 01/19 & 10/28; Windsock Lights - CTAF.
Actvt Rotg Bcn - CTAF.


Charts: NACO: Fairbanks Sectional

Phone: 907-442-3147

Weather: 907-445-2146 (AWOS-3P)

Communication Freqs:
132.1 WX
122.7 CTAF

Elevation: 293 ft (89.3 m)



Notes:
Unattended
Caribou In vicinity of Ry.
Cold Temperature Airport. Altitude Correction Required At or Below -36C.
Ry Conditions not Monitored; Recommend Visual Inspection Prior to Landing.
Wx Camera Avbl on Internet At [Https://Weathercams.FAA.Gov](https://Weathercams.FAA.Gov)
Crowns in Center & No Line of Sight Btw Rwy Ends.
Rwy Surface is Compacted Gravel, Rock and Dirt. Surface Type Listed As Gravel-Dirt.
Rwy Slopes Uphill East to West Appx 80 Ft.
Rwy Surface is Compacted Gravel, Rock and Dirt. Surface Type Listed As Gravel-Dirt.

